Approved For Release 2001/07/28 : CIA-RDP75B00446R000100200018-1

PRIORITY

FILE INFO

AUG 71496338

REPRODUCTION PROHIBITED

7 AUG 74 08 25Z

ACTION							
	1		6		11	16	
	2		7		12	17	
	3		8		13	18	
	4		9		14	19	
	5		10		15	20	

NNNNS E C R E T #7#655Z AUG 74 CITE [redacted] 25X1A

25X1C
25X1A PRIORITY [redacted]

1. 2 EACH MODEL 548T POWER AMPLIFIERS MALFUNCTIONING AND BEYOND LOCAL REPAIR DUE LACK HARNESS AND TEST BOX. NO SPARES REMAIN TO SUPPORT TWO SYSTEMS IN USE. REQUEST PROVIDE 2 REPLACEMENTS ASAP.

25X1A 2. [redacted] ADVISED [redacted] THAT 1 BOX FX23994 13[redacted]6XXX, SHIPPED. BOX CONTAINED AMONG, OTHER THINGS, TWO MODEL 636X POWER SUPPLIES AND ONE 548T POWER AMPLIFIER. INSTRUCTIONS WERE 25X1A FOR [redacted] TRANSHIP TO [redacted] FOR REPAIR AND RETURN PER [redacted] 25X1A 3738.

3. PLEASE ADVISE WHEN CAN EXPECT P.A. REPLACEMENTS. SUGGEST 2 EA 636 POWER SUPPLIES BE SENT [redacted] FOR USE IN REMAINING 25X1A BW PACKAGES. E-2 IMPDET

S E C R E T

BT

#1094

Return to Files

7 AUG 1974

CHIEF DEPUTY
EXEC SUP
TECH SERVICES
SEC ADMIN
FILE [redacted] 25X1C

PRINTED BY THE STANDARD REGISTER COMPANY, U. S. A.

Approved For Release 2001/07/28 : CIA-RDP75B00446R000100200018-1